


Flixborough Disaster 1st June 1974


Andy Brazier


Mob: (+44) 07984 284642 andy@abrisk.co.uk www.abrisk.co.uk







Caprolactam $(CH_2)_5C(O)NH$
















What were they thinking?



Management of Change (MoC)









Trevor Kletz Compendium

His Process Safety Wisdom Updated for a New Generation



What you don't have can't leak






People who aren't there can't be harmed



There are two types of design

- 1. Simple so there are obviously no deficiencies,
- 2. Complicated so there are no obvious deficiencies



→ gas loss

Severity High High Medium Probability Medium Medium Low Medium Low Low Inherently safe

MOST EFFECTIVE

ELIMINATION

PHYSICALLY REMOVE THE HAZARD

SUBSTITUTION

REPLACE THE HAZARD

ENGINEERING CONTROLS

ISOLATE PEOPLE FROM THE HAZARD

ADMINISTRATIVE CONTROLS

CHANGE THE WAY PEOPLE WORK

PPE

PPE IS AN EXAMPLE OF MITIGATION INTENDED TO PROTECT WORKERS AFTER CONTROL OF HAZARD

LEAST EFFECTIVE

Paul Fitts – 1950's

People are better than machines at:

Detection Perception Judgement


Induction Improvisation Long term memory

Machines are better than people at:


Speed Power Computation

Replication Simultaneous operation Short term memory






1 June 1974



31 July 1974



Health and Safety at Work etc. Act 1974





If you would like any more information you can contact me as follows:

Email - andy@abrisk.co.uk

▶ Phone – +44 7984 284642

